

OPERATION MANUAL

TVC MATPRO059 - 2 m Tape Measure with DSC Logo

1. Product Identification

Product marketed by TVC as a 2-meter tape measure with DSC logo. Published model: **FlexometroDSC**. TVC part number: **DSC3010003**.

2. Scope of This Manual

TVC does not publish a manufacturer-specific operation manual for this item on the consulted product page. Therefore, the instructions below are **general operating guidance for a retractable tape measure** and should not be interpreted as official DSC/TVC-specific instructions.

3. Basic Operation

1. Hold the tape measure housing firmly before extending the blade.
2. Pull the tape straight toward the point to be measured without forcing or sharply bending it.
3. Position the end of the tape at the starting point of the measurement.
4. Read the measurement on the tape scale at the ending point of the object or distance being measured.
5. If the product includes a lock, use it only to temporarily hold the tape in the extended position.
6. Release the lock, if applicable, and allow the tape to retract in a controlled manner. Do not let it snap back.

4. Safety Recommendations

- Keep fingers away from the edge of the tape during retraction.
- Do not use the tape as a cutting tool, tie-down, lever, or load-support device.
- Do not extend the tape beyond its practical range if it begins to deform or lose stability.
- Avoid contact with energized electrical conductors because the product page does not indicate electrical insulation.
- Do not allow children to use the product without supervision.

5. Care and Storage

- Keep the tape clean and dry.
- Remove dust or moisture before fully retracting the tape.
- Avoid heavy impacts, crushing, or prolonged exposure to moisture.
- Store the tape measure with the tape fully retracted in a dry place.

6. Inspection Before Use

Visually inspect the tape for tears, excessive bends, or damage, and verify that the retraction mechanism operates in a controlled manner. If damage could cause an uncontrolled snap-back or unreliable reading, discontinue use.

7. Information Limitations

The consulted source only confirms the commercial identification of the product and its 2-meter length. Measurement accuracy tolerances, calibration instructions, internal maintenance, replaceable parts, and repair procedures are not published.

8. Product Data

Brand	DSC
Model	FlexometroDSC
TVC Part Number	DSC3010003
SAT Code	27111801

Specified Length	2 meters
------------------	----------

Source: TVC product page, item 58443. General operating instructions were added only to support safe use of a tape measure and are clearly distinguished from officially published product information.